

## Tongala

**Public Swimming Pool Overview** 

## Overview

**Requirements** The 2018 Aquatic Facilities Review identified the Tongala swimming pool and its facilities require complete renovation to meet minimum industry standards. Pool and buildings require Immediate To meet To meet the extensive overhaul maintenance works minimum compliance minimum industry The area fails to meet disability requirements required standards access requirements • The pool infrastructure (eq. pumps Cost: \$40,000 Cost: \$246,000 Cost: \$777,000 and filters) is deteriorating and frequently break down. Loss per Visit

4

