

Rochester

Public Swimming Pool Overview



Overview


The 2018 Aquatic Facilities Review identified the Rochester swimming pool and its facilities require complete renovation to meet minimum industry standards.

- Pool and buildings require extensive overhaul
- The area fails to meet disability access requirements
- The pool infrastructure (eg. pumps, filters, fencing, lighting, seating) require extensive overhaul.


Requirements

| | | |
|---|--|---|
| ! | ✓ | ✓✓ |
| Immediate maintenance works required | To meet minimum compliance requirements | To meet the minimum industry standards |
| Cost: \$30,000 | Cost: \$862,000 | Cost: \$3,600,000 |

Income versus Cost



Loss per Visit



Fast Facts

- › The school used the pool for one day for their Carnival in March 2021 and physical education classes
- › The Rochester Swim Club undertook eight weekly one hour training sessions for five participants
- › No classes or programs are offered at the pool
- › The pool was built in the 1950s
- › The majority of users come from within a radius of 15km

There is currently
1 pool
(private & commercial)
for every
15 people
in Campaspe,
with that number
set to increase

